

## 1994 Hawker 1000



Serial #: 259042  
Registration: N542LR

Last Updated: 10/29/2010

Airframe:  
Total Time: 10271.1 TT

6647 Cycles

Engines: ESP Silver  
LH Engine: S/N CB-0002  
8770.4 TT 5713 Cycles

Pratt & Whitney PW305B  
RH Engine: S/N 305068  
8313.4 TT 5246 Cycles



APU: Solar T-62T-40C8D1  
S/N SPE-945326

Avionics:

Honeywell SPZ-800 5-Tube

COM: Dual Honeywell RCZ-833 w/8.33  
NAV: Dual Honeywell RNZ-850 w/ FM Im.  
FMS: Dual Honeywell NZ-2000 w/ 6.0a Soft.  
Autopilot: Dual Honeywell DFZ-800  
Flight Director: Dual Honeywell DFZ-800  
Radar: Sperry Primus 870  
ADR: Dual Honeywell DF-850  
DME: Dual Honeywell DM-850  
RMI: Dual Honeywell RNZ-850  
GPS: Single 12 Channel

Audio Panel: Dual Honeywell AV-850A  
Transponders: Dual Honeywell RCZ-850  
Radar RT-300  
Altimeter:  
Traffic Collision: TCAS 2000 w/ Change 7  
CVR: Fairchild A100A  
HF COM: Dual KHF-950  
Flight Phone: Aircell ST-3100 Iridium SATCOM  
EGPWS: Honeywell Mark V  
ELT: Artex 406

Features:

Dual Laserefø  
RVSM Compliant  
DL-950 Data Loader

PAX Briefing  
LSZ-850 Lightning Sensor  
Provisions for FDR

Interior:

Completed in 2005 Bulkhead Monitor w/ Airshow 400  
Seating: 9 (Forward Club, Aft Half Club, 3 place Divan)  
CD/DVD Player.  
Forward Galley w/ Microwave.

Exterior:

Overall Matterhorn White with Windfield Bronze & Oak Brown Stripes and Pearl Gold Accent Stripes.

Maintenance: Complete Log Books. Inspections due in:

A Inspection: 112 hrs C Inspection: 1035 hrs E Inspection: c/w 3/11 G Inspection: c/w 3/14  
B Inspection: 435 hrs D Inspection: 1035 hrs F Inspection: c/w 3/12 48 Month: c/w 3/14