

## 1992 Hawker 1000



Serial #: 259017  
Registration: N517LR

Last Updated: 10/29/2010

Airframe:  
Total Time: 7772.5 TT

4654 Cycles

Engines:  
LH Engine: S/N 305118  
7458.5 TT 4508 Cycles  
Engine on ESP Silver

Pratt & Whitney PW305B  
RH Engine: S/N 305119  
7398.8 TT 4472 Cycles  
Engine on ESP Silver

APU: Solar T-62T-40C9

S/N K00023

Avionics:

Honeywell SPZ-800 5-Tube

COM:  
NAV: Dual Honeywell RNZ-850  
FMS: Dual Honeywell NZ-920  
Autopilot: Dual Honeywell DFZ-800  
Flight Dir: Dual Honeywell DFZ-800  
Radar: WU-870  
ADR: Dual Honeywell RNZ-850  
DME: Dual Honeywell RNZ-850  
RMI: BDI  
Audio Panel: Dual Honeywell AV-850

Dual Honeywell RCZ-850  
Transponders: Dual Honeywell RCZ-850  
Radar Altimeter: RT-220  
Traffic Collision: TCAS II w/ Change 7  
CVR: Fairchild A100A  
HF COM: King KHF-950 w/ SELCAL  
Flight Phone: Aircell ST-3100 Iridium Satcom  
EGPWS: Honeywell Mark V  
ELT: D&M 14-1-1



Features:  
Dual Laserefø  
Global AFIS  
LSZ-850 Lightning Sensor

Interior:

**New Oct 2010**  
Seating: 9 (Forward Club, Aft 1/2 Club, 3 pl. divan)  
Bulkhead monitors w/ Airshow 400  
CD/VHS Players  
Forward Galley with Microwave  
Forward Baggage Closet

Exterior:

Overall Matterhorn White with Winfield Bronze & Oak Brown Stripes and Pearl Gold Accent Stripes.

Log Books: Complete

Maintenance Due: Inspections Current

A Inspection: 177 hrs . C Inspection: 923 hrs E Inspection 09/12 G Inspection 11/12  
B Inspection: 151 hrs D Inspection: 870 hrs F Inspection 01/11 48 Month 11/12

SPECIFICATIONS SUBJECT TO VERIFICATION UPON INSPECTION